

SERVICE BULLETIN NO. SB-7-44400

DATE AND TIME OF REPORT: 5th of August 2021.

SUBJECT: LAT-38-135-H rear suspension hanger

Versalift have been notified of an in-service one-off incident on the LAT-38-135-H pickup installation. During transport the air suspension U-bolt clamps, used to secure the suspension to the chassis and rear axle, have loosened leading to movement between the axle and the chassis.



Versalift ask, that in the first instance, end users inspect the U-bolt clamps to ensure they are secure and that the bolts have not loosened (the torque values for these bolts is 68Nm). If the bolts/ clamps are found to be loose then all work(s) must be stopped and Versalift informed.

Following a thorough investigation, currently underway, Versalift will carry out additional checks at the vehicles' next LOLER.

If you have any questions, or if further information is required, please contact the Versalift After Sales department on +44(0)1536 721010.

Issued By: Tom Johnson CEng MIMechE Tech IOSH

Position: Operations Manager

Signature: 