

SERVICE



BULLETIN



**PLEASE NOTE
THE SERVICE
DEPT FAX
NUMBER
01536 721110**

TO: All Versalift Users

SUBJECT: Emergency Motor Operation

SERVICE BULLETIN REF. 06/0801

DATE: August 2006

A number of cases of the emergency pump failing to operate have been reported, which on investigation have been found to be caused by the emergency motor solenoid sticking. Investigation has shown that the solenoids almost invariable stick due to lack of use.

It is important that the emergency motor is tested from both ground and bucket controls as part of the routine daily checks carried out on the machine. During this check the it is only necessary to operate the emergency motor for a few seconds from both control positions and as well as being an important part of the daily checks will ensure that the solenoid does not stick.

This bulletin is for technical information purposes only and does not constitute authority for mandatory replacement of parts or warranty claim submission.

If you have any questions, or if further information is required, please contact the Versalift Technical Help Line on 01536 721010

**Versalift Distributors (UK) Ltd 1 Altendiez Way Latimer Park Burton Latimer Northants. NN15 5YZ
Tel. 01536 721010 Fax 01536 721110 Email: admin@versalift.co.uk**